

CD150M/NC ELECTRIC MOTOR DRIVEN BEARING BRACKET

SEAL KIT : SK20

ITEMS NOT SHOWN:


1. ITEMS 19 & 22 ARE LIP SEAL SLEEVES FOR SHAFT REPAIR.


2. ITEM 20 SEAL BONDED RUBBER FOR MECH SEAL OIL CHAMBER DRAIN PLUG


PARTS CONTAINED IN SEAL KIT ARE NOT RETURNABLE.
WHEN ORDERING INDIVIDUAL SPARE PUMP PARTS, PLEASE DO NOT
USE THE NUMBERS ON THIS SHEET.
THESE NUMBERS ARE FOR SEAL KIT REFERENCE ONLY - PLEASE I

THESE NUMBERS ARE FOR SEAL KIT REFERENCE ONLY - PLEASE REFER TO THE PARTS BREAKDOWN FOR THE UNIT.

PLEASE BE AWARE THAT ALL LARGE DIAMETER GASKETS/SHIMS ARE ALSO CONTAINED AT THE BOTTOM OF THIS PACKAGING BOX.







MECHANICAL SEAL ASSEMBLY COMMON TO CD150M & NC PUMPS

25	6	41-0241-6112	TOLERANCE RING
24	6	43-0763-9912	SEAL BONDED RUBBER
23	1	38-1312-4112	O RING
22	1	38-1767-6112	LIP SEAL SLEEVE
21	3	38-0809-4112	LIP SEAL
20	1	43-0733-9912	SEAL BONDED RUBBER
19	1	38-1751-6112	LIP SEAL SLEEVE
16	1	38-1033-4112	LIP SEAL
15	1	38-1034-5443	GASKET
8	1	38-1036-4112	O RING
7	1	38-1446-9912	SEAL FACE
6	1	38-1445-9912	MECHANICAL SEAL
5	1	41-0586-9911	CIRCLIP
4	1	38-0700-4112	O RING
3	1	38-0620-9913	SEAL SEAT
2	1	38-1004-4112	O RING
Pos	Qty	PartNo	Description SK20

		TOLERANCES funiess otherwise stated			CREATED BY	DRG NO.	
	Xylem Water	HACHINIS	FABRICATION		Osborn, Stewart - Xylem	∐SK20.MI	
	Services Ltd.	Above 500 ± 0.75 50 to 500 ± 0.4	Above 1000 + 5,0 500 to 1000 + 3,0		CREATED ON	TITLE SEAL KIT	
godwin 😉	Cirencester	0 to 50 + 0.25	125 to 500 + 15	l (⊕) − ∈ 	Wed Oct 21 15		
a xylem brand	Gloucestershire	1 dec. place = 0,1	0 to 125 ± 0.75	THIRD ANGLE PROJECTION	MODIFIED BY	NC80/100/150 ENG/ELEC SETS	
e xyrem orane	GL7 5BX, UK.	Angular • 0°15'	Angular • 0*30*	TPS TO BS 8888:2013	Osborn, Stewart - Xylem		
	Tel: +44 00 1285 750271 Fox: +44 10 1285 750952	GA's & ASSEMBLES	FLATNESS		MODIFIED ON	Proprietary	REV.
	www.godwinpumpa.co.uk	Above 500 ± 0.75	Above 1000 + 3.0 250 to 1000 + 2.0	SURFACE FINISH: microns	Wed Oct 21 15	and Confidential	4.1

